

Investigation Committee on the Accident at Fukushima Nuclear Power Stations of Tokyo Electric Power Company (TEPCO)

Fukushima Dai-ichi NPS Inspection Tour

A team comprising the members of the Investigation Committee on the Accident at Fukushima Nuclear Power Stations of Tokyo Electric Power Company, international experts and others visited the Fukushima Dai-ichi NPS for an inspection tour.

1. Date

February 23, 2012 (Thursday)

2. Participants

- ***Committee members and technical advisor:*** Dr. Hatamura (chairperson), Mr. Yanagida (deputy chairperson), Mr. Takasu (committee member) and Dr. Fuchigami (technical advisor)
- ***International experts:*** Dr. Richard A. Meserve, Mr. Andre-Claude Lacoste, Dr. Lars-Erik Holm, Prof. Chang Soon Heung, and Mr. Chai Guohan
- * ***Secretariat:*** Secretary General and others (including experts)

3. Itinerary

- ◇ Explanation about the overview of Fukushima Dai-ichi NPS (at the J village)
- Exchange of opinions at the seismic isolation building
- Plant tour:
 - Units 1-4, looking at the appearance and visiting seaside facilities
 - Common spent fuel storage facility
 - Seawater system facilities for Units 5 and 6
 - Emergency diesel generators
 - Control room for high level radioactive water treatment facility
 - Reactor feed pump
 - Buffer tank for reactor feed water
- ◇ Q&A (at the J village)