

Final Report

(Attachments)

July 23, 2012

Investigation Committee on the Accident at Fukushima Nuclear

Power Stations of Tokyo Electric Power Company

This page intentionally left blank.

Table of contents

Attachment for Chapter II

Attachment II-1-1: Investigation Results Concerning the Damage to Major Systems and Facilities	1
Attachment II-1-1-1: Unit 1: Reactor Water Level	311
Attachment II-1-1-2: Unit 1 Reactor Pressure	312
Attachment II-1-1-3: Unit 1 Reactor Pressure Vessel (RPV) Temperature	313
Attachment II-1-1-4: Unit 1 Temperatures at the Vessel Bottom	314
Attachment II-1-1-5: Unit 1 D/W Pressure	315
Attachment II-1-1-6: Unit 1 Temperatures around D/W HVH	316
Attachment II-1-1-7: Unit 1 Containment Atmosphere Monitoring System	317
Attachment II-1-1-8: Unit 1 Radiation Monitor of Stack	318
Attachment II-1-1-9: Radiation Dose Rates at Monitoring Posts (MP)	319
Attachment II-1-1-10: Logic Flow of the Startup LOCA Signal Actuation	322
Attachment II-1-1-11: Unit 1 Main Steam Flow and APRM Output	324
Attachment II-1-1-12: Unit 1 D/W Pressure, D/W Temperature, S/C Pressure and S/C Water Temperature	325
Attachment II-1-1-13: Unit 1 PLR Pump (A)(B) Inlet Temperature	326
Attachment II-1-1-14: Unit 1 Inlet Pressure of the Isolation Condenser (IC) Tank	327
Attachment II-1-1-15: Unit 1 Water Level of the Isolation Condenser (IC) Tank	328
Attachment II-1-1-16: Unit 1 Water Temperature of Isolation Condenser (IC) Tank	329
Attachment II-1-1-17: Unit 1 HPCI Turbine Inlet Pressure	330
Attachment II-1-1-18: Unit 1 Overview of the Power Supply Regarding HPCI	331
Attachment II-1-1-19: Unit 2: Reactor Water Level and Pressure	332
Attachment II-1-1-20: Unit 2 Reactor Pressure Vessel (RPV) Temperature	333
Attachment II-1-1-21: Unit 2 Reactor Containment Vessel Nitrogen Gas Pressure	334
Attachment II-1-1-22: Unit 2 Drywell (D/W) Cooler HVH Temperature	335
Attachment II-1-1-23: Unit 2 Containment Atmosphere Monitoring System	336
Attachment II-1-1-24: Unit 2 Operation of SRV	337
Attachment II-1-1-25: Unit 2 PLR Pump Inlet Temperature	338
Attachment II-1-1-26: Unit 2 Main Steam Flow Rate and APRM Output	339
Attachment II-1-1-27: Unit 2 Water Level of the Floor Drain Sump in D/W	340

Attachment II-1-1-28: Unit 2 Standby Gas Treatment System (SGTS) Exhaust Radiation Monitor	341
Attachment II-1-1-29: Unit 2 S/C Water Level	342
Attachment II-1-1-30: Unit 2 Decrease in Water Temperature in S/C due to Cooling Water	343
Attachment II-1-1-31: Unit 2 RCIC Pump Discharge Flow Rate etc.	344
Attachment II-1-1-32: Unit 2 RCIC Pump Discharge Pressure etc.	345
Attachment II-1-1-33: Unit 2 Overview of the Power Supply Regarding HPCI	346
Attachment II-1-1-34: Unit 3 Reactor Water Level	347
Attachment II-1-1-35: Unit 3 Reactor Pressure Vessel (RPV) Temperature	348
Attachment II-1-1-36: Unit 3 Reactor Containment Vessel Nitrogen Gas Pressure	349
Attachment II-1-1-37: Unit 3 Air Temperature Supplied by D/W HVH	350
Attachment II-1-1-38: Unit 3 Containment Atmosphere Monitoring System	351
Attachment II-1-1-39: Unit 3 Main Stack Radiation Monitor	352
Attachment II-1-1-40: Unit 3 Operation of SRV	353
Attachment II-1-1-41: Unit 2 Main Steam Flow Rate and APRM Output	354
Attachment II-1-1-42: Unit 3 PLR Pump Inlet Temperature	355
Attachment II-1-1-43: Unit 3 Alarm Typer	356
Attachment II-1-1-44: Unit 3 Reactor Water Level and Reactor Pressure	357
Attachment II-1-1-45: Unit 3 Shift Operators' Logbook	359
Attachment II-1-1-46: Unit 3 Reactor Pressure	360
Attachment II-1-1-47: Unit 3 Structure of the SRV	361
Attachment II-1-1-48: Unit 3 Reactor Pressure	362
Attachment II-1-1-49: Unit 3 Standby Gas Treatment System (SGTS) Radiation Monitor	363
Attachment II-1-1-50: Unit 3 S/C Water Level	364
Attachment II-1-1-51: Unit 3 Analysis Results of the Reactor Pressure and D/W Pressure	365
Attachment II-1-1-52: Unit 3 Containment Vessel Temperature	366
Attachment II-1-1-53: Unit 3 Reactor Water Level and RCIC Operation	367
Attachment II-1-1-54: Unit 3 Reactor Water Level, RCIC Pump Discharge Pressure etc.	368
Attachment II-1-1-55: Response at the Unit 1 and the transition of indicated values shown by instrumentation devices	369
Attachment II-1-1-56: Response at the Unit 2 and the transition of indicated values shown by instrumentation devices	370

Attachment II-1-1-57: Response at the Unit 3 and the transition of indicated values shown by instrumentation devices	371
Attachment II-1-2: Errors with Reactor Pressure Indicator	372
Attachment II-1-3: Error with Reactor Water Level Indicator	373
Attachment II-2-1: Unit 1 and Unit 3 Hydrogen Explosion Images	376
Attachment II-2-2: Damaged Condition of Unit 1 R/B 5th Floor	377
Attachment II-2-3: Main Causes of Hydrogen Generation inside the R/B	378
Attachment II-2-4: Amount of Hydrogen Generated at Unit 1	379
Attachment II-2-5: Possible Locations of Hydrogen Leakage from Containment	380
Attachment II-2-6: Damaged Condition of Unit 2 R/B 5th Floor	381
Attachment II-2-7: Locations of Seismic Observation Recorders within the Fukushima Dai-ichi Nuclear Power Station	382
Attachment II-2-8: Damaged Condition of Unit 3 R/B	392
Attachment II-2-9: Amount of Hydrogen Generated in Unit 3 and Unit 4	395
Attachment II-2-10: Damaged Condition of Unit 4 R/B	396
Attachment II-2-11: Possible Inflow Pass of Hydrogen from Unit 3 to Unit 4	399
Attachment II-3-1: Timeline of operator Actions to Achieve Cold Shutdown at Unit 5 and Unit 6 of the Fukushima Dai-ichi NPS	401
Attachment II-3-2: Illustrated Overview of Reactor Water Levels (Fukushima Dai-ichi NPS Unit 5 and 6)	402
Attachment II-3-3: Schematic Drawing of Power Restoration at Unit 5 and Unit 6 of the Fukushima Dai-ichi NPS	403
Attachment II-3-4: Overview of the System Configuration at Unit 5 of the Fukushima Dai-ichi NPS	404
Attachment II-3-5: Overview of the system Configuration at Unit 6 of the Fukushima Dai-ichi NPS	405
Attachment II-4-1: Electrical Installations Inside and Outside the Fukushima Dai-ichi NPS Site	406
Attachment II-4-2: Fukushima Dai-ichi Nuclear Power Station Layout Drawing	407
Attachment II-4-3: The Damage to Electrical Installations Inside and Outside the Fukushima Dai-ichi NPS Site	408
Attachment II-4-4: Main Damages at the Shin Fukushima Substation	409
Attachment II-4-5: Review results on the Restoration of External Power for the Fukushima Dai-ichi NPS (Reviews on the restoration of external power for Unit 1 to Unit 4 Part 1: as of the noon March 12)	410

Attachment II-4-6: Review results on the Restoration of External Power for the Fukushima Dai-ichi NPS (Reviews on the restoration of external power for Unit 1 to Unit 4 Part 2: until the explosion at the Unit 3 R/B)	411
Attachment II-4-7: Restoration of External Power for the Fukushima Dai-ichi NPS (Restoration of External Power for Unit 1 and Unit 2: Utilization of the TEPCO nuclear power line)	412
Attachment II-4-8: Restoration of External Power for the Fukushima Dai-ichi NPS (Restoration of External Power for Unit 3 and Unit 4: Utilization of the Yonomori and Okuma power transmission lines)	413
Attachment II-4-9: Restoration of External Power for the Fukushima Dai-ichi NPS (Restoration of External Power for Unit 5 and Unit 6: Utilization of the Yonomori Power Line 2L)	414
Attachment II-4-10: Restoration of External Power for the Fukushima Dai-ichi NPS (Stabilization measures for external power, implemented by July)	415
Attachment II-5-1: Sequential Outline of Reactors to Cold Shutdown at the Fukushima Dai-ni NPS	416
Attachment II-5-2: Facilities at the Fukushima Dai-ni NPS	417
Attachment II-5-3: General Layout of the Fukushima Dai-ni NPS	418
Attachment II-5-4: Overview of the Systems Configuration at Unit 1-4 of the Fukushima Dai-ni NPS	419
Attachment II-5-5: Overview of the Electrical Installations both on- and off-site the Fukushima Dai-ni NPS	420
Attachment II-5-6: Investigation Results Concerning the Flooding of the Fukushima Dai-ni NPS by the Tsunami (Level of inundation, water depth and flooded areas)	421
Attachment II-5-7: The Damage to the Emergency DG, M/C and P/C at the Fukushima Dai-ni NPS	422
Attachment II-5-8: Flooding Conditions at the Seawater Heat Exchanger Building of Unit 1-Unit 4, the Fukushima Dai-ni NPS	423
Attachment II-5-9: Diagram of the Reactor Water Level of Unit 1-4 at the Fukushima Dai-ni NPS	429
Attachment II-5-10: Organization at the Fukushima Dai-ni NPS	430
Attachment II-5-11: Layout of the Emergency Response Office at the Fukushima Dai-ni NPS	431
Attachment II-5-12: Fukushima Dai-ni NPS, Unit 1 The Mechanism of Recording “MSIV Reactor Low Water Level (L-2)”	432

Attachment II-5-13: Outline of the RHR Operation Mode at Unit 1-4 of the Fukushima Dai-ni NPS	433
---	-----

References

Investigation Committee on the Accident at the Fukushima Nuclear Power Stations of Tokyo Electric Power Company: timeline of activities (2011)	434
Establishment of the Investigation Committee on the Accident at the Fukushima Nuclear Power Stations of Tokyo Electric Power Company	436
Rules on the establishment of the Secretariat of the Investigation Committee on the Accident at the Fukushima Nuclear Power Stations of Tokyo Electric Power Company	437
Structure of the Investigation Committee on the Accident at the Fukushima Nuclear Power Stations of Tokyo Electric Power Company	438
List of experts (policy and technical investigation advisors) at the Secretariat of the Investigation Committee on the Accident at the Fukushima Nuclear Power Stations of Tokyo Electric Power Company	439
Management procedures of the Investigation Committee on the Accident at the Fukushima Nuclear Power Stations of Tokyo Electric Power Company	441
Information and informative materials to be handled without disclosure	443
Methods of Interview	445
Summary of opinions and advice offered by international experts at the Eighth Committee Meeting (February 24 and 25, 2012)	448
List of English abbreviations	452

This page intentionally left blank.